

**ABSTRACT**

Method of repairing defective areas in a stoving lacquer coating, in which the defective area ready for repair lacquering is coated with a powder coating composition or with an aqueous powder coating slurry, and the applied powder coating is then melted and cured by irradiation with near infrared radiation (NIR).